

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 1-W-27

Location ID: 335168

Date: 11/4/2024



Southwest Corner of Location – Photo #04696



Location – Photo #04697

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 1-W-27

Location ID: 335168

Date: 11/4/2024



Location – Photo #04698



Location – Photo #04701

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 1-W-27

Location ID: 335168

Date: 11/4/2024



Lack of Stabilization – Photo #04699



Lack of Stabilization – Photo #04700

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 1-W-27

Location ID: 335168

Date: 11/4/2024



Insufficient Tracking BMPs – Photo #04702