

Final Reclamation Inspection

October 21, 2024

Operator: TOP OPERATING COMPANY - 39560

Location ID: 330147

Inspection Document #: 697505547

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LONGMONT #8-10K
Location ID: 330147



Photo 1. Photo taken on June 9, 2022 from the central location, facing North. Photo illustrates the northern location was dominated by annual, weedy vegetation. The southern location had the establishment of desirable vegetation.



Photo 2. Photo taken on October 21, 2024 from the northern location, facing West. Photo illustrates additional reclamation activities were performed and desirable vegetation establishment was observed.

Note- reclamation areas had more establishment of perennial vegetation than the adjacent western and northern reference areas.

Inspection Photos
Location Name: LONGMONT #8-10K
Location ID: 330147



Photo 3. Photo taken on October 21, 2024 from the northern location, facing East. See comments under Photo 2.



Photo 4. Photo taken on October 21, 2024 from the northern location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: LONGMONT #8-10K
Location ID: 330147



Photo 5. Reference photo taken on October 21, 2024 west of the location, facing Southwest. Photo illustrates both annual and perennial vegetation establishment.