

Final Reclamation Inspection

October 21, 2024

Operator: TOP OPERATING COMPANY - 39560

Location ID: 331060

Inspection Document #: 697505551

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 1. Photo taken on May 26, 2022 from the well location, facing West. Photo illustrates all equipment has been removed from location and final reclamation have been completed. However, there was very little establishment of desirable vegetation and mostly consisted of weedy annual vegetation.



Photo 2. Photo taken on October 21, 2024 from the well location, facing West. Photo illustrates the current reclamation progress. Photo does not demonstrate effectively but there was some germination of desirable vegetation.



Inspection Photos
Location Name: EVANS #6
Location ID: 331060



Photo 3. Photo taken on May 26, 2022 from the well location, facing Southeast. See comments under Photo 1.



Photo 4. Photo taken on October 21, 2024 from the well location, facing Southeast. See comments under Photo 2.