

WELL SITE INSPECTION FORM

C

Well Name Anderson #1 API Number 05 - 103 - 074630
 Operator Dyco Petroleum Permit # 720603
 Location NE 1/4 17-T1N-R93W County Rio Blanco
 Field Wildcat Inspector B. Macke

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) _____ Fail(N) X Date 12/30/91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES _____ NO _____ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
 Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes _____ No _____
 Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 10/14/72 Date Permit Expired: _____
 Hole Plugged: Yes X No _____ Pits Backfilled: Yes X No _____
 Material Buried: Yes _____ No X N/A _____ Site Clean: Yes _____ No X
 Bond Release OK: Yes X No X Fed _____ Hole Marker: Yes X No _____

Pipe marker

Date of Safety/Status Inspection 12/30/91

Comments: Gained access through nearby landowner's property

- met

6" x 12" on ground during PA inspection - hiked 1/3 mile in.
Crushed steel drum + 7' long 18" diam. corrugated culvert + pipe
lying on location. Otherwise, location cleared + leveled - mostly
revegetated w/ sagebrush.
Pipe marker inscribed w/ well name, loc. + operator.

(Also an old board by the pipe marker)



00038411

Violations: Yes _____ No X Notice Sent: Yes _____ No _____ Date Sent: _____