

Final Reclamation Inspection

October 30, 2024

Operator: RENEGADE OIL & GAS COMPANY LLC - 74165

Location ID: 418097

Inspection Document #: 697505555

Arapahoe County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 1. Photo taken from the western portion of the access road, facing East. Photo illustrates this section is dominated by annual, weedy vegetation.

Note- this section of road may get re-disturbed by another Operator on a new, proposed oil and gas location.



Photo 2. Photo taken from the approximate halfway point of the access road, facing East. Photo illustrates the establishment of introduced, perennial grasses (Crested wheatgrass), which was not part of the SLB seed mixture.

See Photo 3 for a close up of Crested wheatgrass.

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 3. Photo illustrates the introduced, perennial Crested wheatgrass.



Photo 4. Photo taken from a portion of eastern access road, facing East. Photo illustrates the establishment of Cheatgrass, a List C noxious weed species.

See Photo 5 for a close up of Cheatgrass.



Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 5. Photo illustrates Cheatgrass.



Photo 6. Photo taken from a portion of eastern access road just west of the location, facing East. Photo illustrates a portion of the access road that was not properly recontoured with evidence of historic erosion. Given the proximity to surface water (creek drainage), this shall be recontoured and long-term stabilization through revegetation.

Also, refer to Photo 11.

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 7. Photo taken from the central location, facing North. Photo illustrates much of the location is weedy, annual vegetation with some germination of perennial grasses. It does not appear that weed management has been performed. Again, perennial grasses are mostly introduced species not reflective of reference areas and not approved by the SLB.



Photo 8. Photo taken from the central location, facing East. See comments under Photo 7.

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 9. Photo taken from the central location, facing South.
See comments under Photo 7.



Photo 10. Photo taken from the central location, facing West.
See comments under Photo 7.

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 11. Google Earth aerial image from March 14, 2022 illustrating the eastern portion of the access road and location. Photo is highlighting an area that needs to be recontoured.

Inspection Photos
Location Name: STATE OF COLORADO #2-33
Location ID: 418097



Photo 12. Reference photo taken along the western boundary of location, facing North. Reference area vegetation to the left of the red-dashed line; reclamation area to the right, which illustrates weedy, annual vegetation.





Photo 13. Photo illustrates the approved surface owner (SLB) seed mixture.