

Inspection Photos  
Location Name: Greasewood 10-20H  
Location ID: 423614



Energy and Carbon Management Commission  
40.47959, -104.24076, 4649.4ft  
10/30/2024 11:31:24



Energy and Carbon Management Commission  
40.4796, -104.24073, 4641.4ft  
10/30/2024 11:31:28

Photo 1 – Tank Battery

Photo 2 – Tank Battery Signs

**Inspection Photos**  
**Location Name: Greasewood 10-20H**  
**Location ID: 423614**



Energy and Carbon Management Commission  
40.47941, -104.24077, 4609.6ft  
10/30/2024 11:31:53

**Photo 3 – Separator and ECD**



Energy and Carbon Management Commission  
40.47954, -104.24109, 4605.9ft  
10/30/2024 11:32:39

**Photo 4 – Pumping Unit**

Inspection Photos  
Location Name: Greasewood 10-20H  
Location ID: 423614



**Photo 5 – Chemical Tank missing Label**



**Photo 6 – Wellhead**