

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840




Photo 1 – Gas Meter Houses

Photo 2 – Wellhead

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Photo 3 – ECD



Photo 4 – Tank Battery

Inspection Photos
Location Name: Mule Deer 6-61-16-4H
Location ID: 428840



Energy and Carbon Management Commission
40.48253, -104.22076, 4625.3ft
10/30/2024 11:40:05



Energy and Carbon Management Commission
40.4824, -104.22108, 4618.6ft
10/30/2024 11:40:23

Photo 5 – Tank Battery Sign

Photo 6 – Separator