

Inspection Photos

November 1st, 2024

Operator: Simcoe LLC - 10749

Location ID: 320865

Inspection Document #: 714001428

Archuleta County, CO

Township: NESW 12 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

November 1, 2024 at 10:32:13 AM MDT
350° N



Photo 1. View of well disturbance taken from the access point facing center. Note: visible salt crust observed on active pad.



November 1, 2024 at 10:33:55 AM MDT
1° N



Photo 2. View of the eastern interim reclamation area facing north. Note: area is dominated predominantly rubber rabbitbrush, no bare soils were observed in this area as noted in previous inspection.

Inspection Photos
Location Name: Luchini 32-6-12 1
Location ID: 320865

November 1, 2024 at 10:40:08 AM MDT
146° SE



Photo 3. View of the location access road, no rutting was observed.

November 1, 2024 at 10:34:23 AM MDT
8° N



Photo 4. View of active pasture reference area.