

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad

Location #: 335323



Photo # 9244 From entrance to location



Photo # 9245 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad

Location #: 335323



Photo # 9246 Location



Photo # 9247 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad

Location #: 335323



Photo # 9248 Location



Photo # 9249 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RMV 238-29 Pad

Location #: 335323



Photo # 9250 Staining near separator unit



Photo # 9251 Hog panels around tank battery & separator units need maintenance