

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 9414 From entrance to location




Photo # 9415 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 9416 Location



Photo # 9417 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 9418 Location



Photo # 9419 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 66-20 Pad

Location ID: 335272



Photo # 9420 Open ended load line