

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2024

Submitted Date:

11/07/2024

Document Number:

716201222**FIELD INSPECTION FORM**Loc ID 435435 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443481	TANK BATTERY	AC	10/02/2015		-	ELLIOTT TANK BATTERY 32N-18HZ	AO

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.228830,-104.927880

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,

Comment:	
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shared with crude oil tanks.
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

