

Inspection Photos

API: 073-06460

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 11/5/2024

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north south of the wellsite. This area was where land farming of cutting had occurred. The vegetation appears to be fully established inside the fence area. This small area along the fence could use additional work.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06460 | Date: 11/5/2024

Inspection Photos



Photo 4. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:073-06460 | Date: 11/5/2024

Inspection Photos



Photo 3. The well sign is posted at the well.

