

# Inspection Photos

API: 073-06437

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 11/5/2024

County: LINCOLN



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:073-06437 | Date: 11/5/2024

## Inspection Photos



**Photo 2.** The sign at the tank battery is faded and needs to be replaced.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:073-06437 | Date: 11/5/2024



## Inspection Photos



**Photo 3.** Facing southeast toward the interim reclamation area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 4.** The well sign is posted at the well.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:073-06437 | Date: 11/5/2024