

Inspection Photos

API: 073-06414

Operator: VECTA OIL & GAS LTD

Inspection Date: 11/5/2024

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing east down toward the location. The location consist mostly of undesirable weeds (Kochia) which needs to be controlled. Additional seeding and weed control need to be performed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06414 | Date: 11/5/2024

Inspection Photos




Photo 2. Drone aerial photo facing southeast down toward the location, The location consist mostly of undesirable weeds (Kochia) which is the dark brown vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06414 | Date: 11/5/2024

Inspection Photos



Photo 3. Drone aerial photo facing north down toward the location. The location consist mostly of undesirable weeds (Kochia) which needs to be controlled. Additional seeding and weed control need to be performed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06414 | Date: 11/5/2024

Inspection Photos



Photo 4. Facing west toward the surrounding pasture.

