

Inspection Photos

API: 073-06485

Operator: WESTERN OPERATING COMPANY

Inspection Date: 11/5/2024

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos




Photo 1. Drone aerial photo facing north down toward the location. There are areas bare of vegetation and undesirable weeds. Perennial vegetation has not sufficiently established.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06485 | Date: 11/5/2024

Inspection Photos



Photo 2. Drone aerial photo facing east down toward the location. There are areas bare of vegetation and undesirable weeds. Perennial vegetation has not sufficiently established.



Inspection Photos



Photo 3. Drone aerial photo facing west down toward the location. There are areas bare of vegetation that need to be reseeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 4. Facing south toward the surrounding pasture.

