

# Inspection Photos

November 1st, 2024

Operator: Petrox Resources INC - 69805

Location ID: 320850

Inspection Document #: 714001444

Archuleta County, CO

Township: NENW 9 34N 5W M

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Fosset Gulch Unit 9U 1A  
Location ID: 320850



**Photo 1.** View of well disturbance taken from the access point facing center. Note: Local emergency contact # has been posted to the location sign.

Inspection Photos  
Location Name: Fosset Gulch Unit 9U 1A  
Location ID: 320850



**Photo 2.** Mullein observed in the southern portion of the disturbance.

Inspection Photos  
Location Name: Fosset Gulch Unit 9U 1A  
Location ID: 320850



**Photo 3.** Unmarked guy line anchor in southern portion of the disturbance.