

# Inspection Photos

November 1st, 2024

Operator: Petrox Resources INC - 69805

Location ID: 320887

Inspection Document #: 714001434

Archuleta County, CO

Township: SWSW 10 34N 5W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Caldelaria 33-5 Fee 10U #3  
Location ID: 320887



**Photo 1.** View of well disturbance taken from the access point facing center. Note: Local emergency contact # has been posted to the location sign.





Inspection Photos  
Location Name: Caldelaria 33-5 Fee 10U #3  
Location ID: 320887



**Photo 2.** View of the northern interim reclamation area composed predominantly of Intermediate Wheatgrass, Smooth Brome and Yellow Sweet Clover.



Inspection Photos

Location Name: Caldelaria 33-5 Fee 10U #3

Location ID: 320887



**Photo 3.** View of Musk Thistle observed in the SW corner and along the eastern edge of the disturbance.



Inspection Photos

Location Name: Caldelaria 33-5 Fee 10U #3

Location ID: 320887



11/1/24  
222° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed of Gambel Oak, Pine and Smooth Brome.

API #: 007-06215