

Inspection Photos

November 1st, 2024

Operator: Petrox Resources INC - 69805

Location ID: 320902

Inspection Document #: 714001441

Archuleta County, CO

Township: SWSE 9 34N 5W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fosset Gulch Unit 9U 4
Location ID: 320902



Photo 1. View of well disturbance taken from the access point facing center. Note: Local emergency contact # has been posted to the location sign.

Inspection Photos
Location Name: Fosset Gulch Unit 9U 4
Location ID: 320902



Photo 2. Large patch of weedy Kochia debris observed in the western interim reclamation/cut slope.

Inspection Photos
Location Name: Fosset Gulch Unit 9U 4
Location ID: 320902

11/1/24
80° E



Photo 3. View of impacted/stained surface material observed at the pump jack.



Inspection Photos
Location Name: Fosset Gulch Unit 9U 4
Location ID: 320902



Photo 4. Patch of Mullein observed in the eastern interim reclamation/fill slope.

Inspection Photos
Location Name: Fosset Gulch Unit 9U 4
Location ID: 320902



Photo 5. Reference area composed of Pine, Gambel Oak and Squirrel Tail.

