

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, TBI PRODUCTION-67S96W/25SESW

Location ID: 324002

Date: 11/5/2024



Nov 5, 2024 at 13:12:28  
Parachute CO 81635  
United States

Location Entrance – Photo #04730



Nov 5, 2024 at 13:12:44  
Parachute CO 81635  
United States

Location – Photo #04731




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, TBI PRODUCTION-67S96W/25SESW

Location ID: 324002

Date: 11/5/2024



Location – Photo #04734



Location – Photo #04732



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, TBI PRODUCTION-67S96W/25SESW

Location ID: 324002

Date: 11/5/2024



Wildlife Entry Hazard – Photo #04735



Wildlife Entry Hazard – Photo #04736



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, TBI PRODUCTION-67S96W/25SESW

Location ID: 324002

Date: 11/5/2024



Wildlife Entry Hazard – Photo #04737



Weeds on Location – Photo #04739