

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

07/18/2024

Document Number:

403858416

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mic  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:  
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION  
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6  
County: WELD Field Name:  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772245 Facility Name: Villani 228631 Facility Type: Domestic Well  
Location: QtrQtr: SESE Sec: 25 Twp: 1N Range: 68W Meridian: 6  
County Name: WELD Latitude: 40.018110 Longitude: -104.944020

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120803 Document Name: Size of file in bytes: 11556 File Name: 2024\_04\_25\_Villani 228631 Trip Blank SGS  
ECMC.xlsx  
SampleType: Matrix:  
Facility ID: 772245 Sample ID: 660435 Sample Name: Villani 228631 Sample Date: 04/25/2024  
Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA63998-1

Batch ID: 120802		Document Name: Size of file in bytes: 28405		File Name: 2024_04_25_Villani 228631 SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 660434	Sample Name: Villani 228631		Sample Date: 04/25/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA63997-1		

  

Batch ID: 120805		Document Name: Size of file in bytes: 11276		File Name: 2024_04_25_Villani 228631 Isotech SIW ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 660438	Sample Name: Villani 228631		Sample Date: 04/25/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 920593		

  

Batch ID: 120804		Document Name: Size of file in bytes: 13418		File Name: 2024_04_25_Villani 228631 Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 660437	Sample Name: Villani 228631		Sample Date: 04/25/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 920658		

  

Batch ID: 120804		Document Name: Size of file in bytes: 13418		File Name: 2024_04_25_Villani 228631 Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772245	Sample ID: 660436	Sample Name: Villani 228631		Sample Date: 04/25/2024	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 920658		

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
772245	403858453	2024_04_25_Villani_228631_Spigot_loc.jpg	Photographs	JPG
772245	403858455	2024_04_25_Villani_228631_Wellhead_loc.jpg	Photographs	JPG
772245	403858450	2024_04_25_Villani_228631_PrePostPurge.jpg	Photographs	JPG
772245	403858441	2024_04_25_Villani_228631_SGS.pdf	Analytical Laboratory Report	PDF
772245	403858448	2024_04_25_Villani_228631_FS_ECMC.pdf	Field Data Report	PDF
772245	403858427	2024_04_25_Villani_228631_Isotech SIW.pdf	Analytical Laboratory Report	PDF
772245	403858454	2024_04_25_Villani_228631_Wellhead.jpg	Photographs	JPG
772245	403858451	2024_04_25_Villani_228631_Spigot.jpg	Photographs	JPG
772245	403858436	2024_02_08_Villani_228631_Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772245	403858429	2024_04_25_Villani_228631_Isotech NG4.pdf	Analytical Laboratory Report	PDF

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	11/11/2024
Total: 1 comment(s)		