

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 03/28/2024 Document Number: 403734495

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306 Address: P O BOX 173779 Fax: () City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number: Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6 County: WELD Field Name: WATTENBERG Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 764985 Facility Name: Reigle 270197 Facility Type: Domestic Well Location: QtrQtr: NENW Sec: 4 Twp: 2N Range: 65W Meridian: 6 County Name: WELD Latitude: 40.173949 Longitude: -104.669679

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 118392 Document Name: Size of file in bytes: 26427 File Name: 2024_01_29_Reigle 270197 SGS ECMC.xlsx SampleType: Matrix: Facility ID: 764985 Sample ID: 657846 Sample Name: Reigle 270197 Sample Date: 01/29/2024 Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA61542-1

Batch ID: 118395	Document Name: Size of file in bytes: 36352	File Name: 2024_01_29_Reigle 270197 Isotech NG4 ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 764985	Sample ID: 657850	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	NOAV Number: _____
Laboratory: ISOTECH		Lab Sample ID: 907851

Batch ID: 118394	Document Name: Size of file in bytes: 11613	File Name: 2024_01_29_Reigle 270197 Trip Blank SGS ECMC.xlsx
SampleType: _____		Matrix: _____
Facility ID: 764985	Sample ID: 657848	Sample Name: Reigle 270197
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	NOAV Number: _____
Laboratory: Accutest		Lab Sample ID: DA61545-1

Batch ID: 118393	Document Name: Size of file in bytes: 9392	File Name: 2024_01_29_Reigle 270197 SGS ECMC DRO.xlsx
SampleType: _____		Matrix: _____
Facility ID: 764985	Sample ID: 657847	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	NOAV Number: _____
Laboratory: Accutest		Lab Sample ID: DA61542-1

Batch ID: 118395	Document Name: Size of file in bytes: 36352	File Name: 2024_01_29_Reigle 270197 Isotech NG4 ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 764985	Sample ID: 657849	Sample Name: Reigle 270197
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	NOAV Number: _____
Laboratory: ISOTECH		Lab Sample ID: 907851

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
764985	403734501	2024_01_29_Reigle 270197 Isotech NG4.pdf	Analytical Laboratory Report	PDF
764985	403734506	2024_01_29_Reigle 270197 SGS.pdf	Analytical Laboratory Report	PDF
764985	403734526	2024_01_29_Reigle_270197_Wellhead.jpg	Photographs	JPG
764985	403734520	2024_01_29_Reigle_270197_PrePostPurge.jpg	Photographs	JPG
764985	403734527	2024_01_29_Reigle_270197_Wellhead_Loc.jpg	Photographs	JPG
764985	403734503	2024_01_29_Reigle 270197 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
764985	403734524	2024_01_29_Reigle_270197_Spigit_Loc.jpg	Photographs	JPG
764985	403734522	2024_01_29_Reigle_270197_Spigit.jpg	Photographs	JPG
764985	403734516	2024_01_29_Reigle_270197_FS_ECMC.pdf	Field Data Report	PDF

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Engineer	The data submitted by the operator can be accessed through COGIS data system.	11/11/2024
Total: 1 comment(s)		