

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0617-41 Pad

Location ID: 324160

Date: 11/06/2024



Photo # 8850 Entrance to location



Photo # 8859 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0617-41 Pad

Location ID: 324160

Date: 11/06/2024



Photo # 8851 Location



Photo # 8854 Location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0617-41 Pad

Location ID: 324160

Date: 11/06/2024



Nov 6, 2024 at 3:52:09 PM
+39.529038,-108.237118 ±4.71m
De Beque



Nov 6, 2024 at 3:59:29 PM
+39.528265,-108.237323 ±4.73m
De Beque

Photo # 8858 Location

Photo # 8868 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC CC/0617-41 Pad

Location ID: 324160

Date: 11/06/2024



Photo # 8869 SW corner of location



Photo # 8865 Open ended load line