

Rhoades 22-35 #2
Attachment B - Photolog
(October 10, 2024)



Description: Stained soil was removed below the disconnected compressor.



Description: Stained soil was removed below the disconnected compressor.



Description: Stained soil was removed around the wellhead by hand.



Description: Stained soil was removed around the connected compressor by hand.



Description: Clean soil was used to fill excavation around disconnected compressor.



Description: Clean soil was used to fill excavation around wellhead.



Description: Clean soil was used to fill excavation around connected compressor.



Description: Clean soil was used to fill excavation around connected compressor.



