

Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 11/7/2024



Location – Photo #04777



Location – Photo #04778

Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 11/7/2024



Location – Photo #04786



Wildlife Entry Hazard – Photo #04780

Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 11/7/2024



Nov 7, 2024 at 12:46:18
5201-5757 County Road 306
Parachute CO 81635
United States

Wildlife Entry Hazard – Photo #04781



Nov 7, 2024 at 12:46:51
5201-5757 County Road 306
Parachute CO 81635
United States

Dead Weeds on Location – Photo #04785