

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

11/04/2024

Document Number:

403980939

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: <u>47120</u>	Contact Person: <u>Dane Olson</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(307) 760-5319</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>Dane_Olson@oxy.com</u>

Identification Information

API Number: <u>05 - 123-36141</u>	ECMC Facility ID: <u>430358</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>REIGLE</u>	Facility Number: <u>2N-4HZ</u>	Facility Type: <u>WELL</u>
Location QtrQtr: <u>SWSE</u>	Section: <u>4</u>	Township: <u>2N</u>
	Range: <u>65W</u>	Meridian: <u>6</u>
	County: <u>WELD</u>	Field Name: <u>WATTENBERG</u>
Federal, Indian or State Lease Number: _____		

Information Submitted By:

Company Name: <u>Absaroka Solutions</u>	Agent Name: <u>Jordan Fleming</u>	Title: <u>Environmental Professional</u>
Phone Number: <u>7202448469</u>	Email: <u>jordan.fleming@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected _____

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>430358</u>	Facility Name: <u>REIGLE 2N-4HZ</u>	Facility Type: <u>Oil and Gas Well</u>
Location: QtrQtr: <u>SWSE</u>	Sec: <u>4</u>	Twp: <u>2N</u>
	Range: <u>65W</u>	Meridian: <u>6</u>
County Name: <u>WELD</u>	Latitude: <u>40.162112</u>	Longitude: <u>-104.667911</u>
Facility ID: <u>0</u>	Facility Name: <u>Ridgeview 32-16-1</u>	Facility Type: _____
Location: QtrQtr: <u>NE/SW</u>	Sec: <u>16</u>	Twp: <u>6N</u>
	Range: <u>91W</u>	Meridian: <u>6</u>
County Name: <u>MOFFAT</u>	Latitude: <u>40.475670</u>	Longitude: <u>-107.610538</u>

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 123211 Document Name: Size of file in bytes: 18637 File Name: 2024_08_06_BW_05_123_36141_BHD_Isotech_NG_4_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 430358 Sample ID: 663134 Sample Name: BW_05_123_36141_BHD Sample Date: 08/06/2024

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 933364

Batch ID: 123211 Document Name: Size of file in bytes: 18637 File Name: 2024_08_06_BW_05_123_36141_BHD_Isotech_NG_4_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 430358 Sample ID: 663135 Sample Name: BW_05_123_36141_BHD Sample Date: 08/06/2024

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 933364

Batch ID: 123213 Document Name: Size of file in bytes: 16828 File Name: 2024_08_06_BW_05_123_36141_BHD_Trip_Blank_SGS_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 0 Sample ID: 663137 Sample Name: BW_05_123_36141_BHD_TRIP_BLANK Sample Date: 08/06/2024

Collection Point: TB Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA66195-1

Batch ID: 123214 Document Name: Size of file in bytes: 18021 File Name: 2024_08_06_SP_05_123_36141_C_Isotech_NG4_ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 430358 Sample ID: 663138 Sample Name: SP_05_123_36141_C Sample Date: 08/06/2024

Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 933292

Batch ID: 123212 Document Name: Size of file in bytes: 23366 File Name: 2024_08_06_BW_05_123_36141_BHD_SGS_ECM_C.xlsx

SampleType: _____ Matrix: _____

Facility ID: 0 Sample ID: 663136 Sample Name: BW_05_123_36141_BHD Sample Date: 08/06/2024

Collection Point: BDH Matrix: WATER Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA66190-1

Sample Facility Attachment:
No Facility Attachment

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
663137	123-36141	REIGLE 2N-4HZ	Trip Blank

General Comments

User Group	Comment	Comment Date
Engineer	The data submitted by the operator can be accessed through COGIS data system.	11/12/2024

Total: 1 comment(s)