

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403990635

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 313-5582
City: DENVER	State: CO	Zip: 80202
Contact Person: Jason Davidson	Email: Jason.Davidson@chevron.com	Mobile: ()

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 24600 Initial Form 27 Document #: 403091614

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-24009	County Name: WELD
Facility Name: FRENZEL B 15-25	Latitude: 40.395921	Longitude: -104.540770	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 15	Twp: 5N	Range: 64W
Meridian: 6	Sensitive Area? No		

Facility Type: SPILL OR RELEASE	Facility ID: 483179	API #: _____	County Name: WELD
Facility Name: Frenzel B 15-25	Latitude: 40.395921	Longitude: -104.540770	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 15	Twp: 5N	Range: 64W
Meridian: 6	Sensitive Area? Yes		

Facility Type: SPILL OR RELEASE	Facility ID: 483475	API #:	County Name: WELD
Facility Name: Frenzel B 15-25	Latitude: 40.395961	Longitude: -104.540858	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NWSW	Sec: 15	Twp: 5N	Range: 64W
Meridian: 6		Sensitive Area? Yes	

SITE CONDITIONS

General soil type - USCS Classifications SW

Most Sensitive Adjacent Land Use grassland

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

HPH N
Freshwater Emergent Wetlands 0.04/0.1mi NW, 0.05/0.17mi W, 0.05mi S
Freshwater Pond 0.05/0.23mi NW
Riverine 0.13mi NW
Structure 0.19mi NW

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached figures	Laboratory analysis
Yes	SOILS	25'x25'x3' deep	Laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to COGCC Rule 911 a site investigation will be conducted pertaining to the FRENZEL B15-25 wellhead cut and cap and flowline removal. Approximately 742' of flowline will be removed. The wellhead was cut and capped per COGCC rules. Additionally, soil samples were collected at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, AS APPLICABLE to abandonment type. The Flowline Pre-Abandonment Notice Document number was previously included under Related Forms.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples were collected along the flowline at any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, AS APPLICABLE to abandonment type. A grab confirmation soil sample was collected at the wellhead excavation. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was encountered during the site investigation. See attached for details

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection along the flowline and at the wellhead and separator areas occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling was required. The applicable ECMC Closure Checklists were utilized and filled out during the abandonment process. A photolog is attached.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 25

Number of soil samples exceeding 915-1 21

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 625

Groundwater

Number of groundwater samples collected 21

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 3

Number of groundwater monitoring wells installed 6

Number of groundwater samples exceeding 915-1 1

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

NA / ND

-- Highest concentration of TPH (mg/kg) 96

-- Highest concentration of SAR 9.57

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 3

-- Highest concentration of Benzene (µg/l) 32.5

-- Highest concentration of Toluene (µg/l) 39.4

-- Highest concentration of Ethylbenzene (µg/l) 7.06

-- Highest concentration of Xylene (µg/l) 46.1

NA Highest concentration of Methane (mg/l)

OTHER INVESTIGATION INFORMATION☐ Were impacts to adjacent property or offsite impacts identified?☒ Were background samples collected as part of this site investigation?

Five background soil samples will be collected during the excavation of impacted soil from similar depths and lithologies as the excavation confirmation soil samples. The background samples will be used to characterize the native soil and potentially attribute elevated metals and inorganic concentrations to native soil conditions. See the attached figure for the proposed background sample locations.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Five additional background samples will be collected during the excavation.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil will be removed from the release area at the Frenzel wellhead and along the flowline by excavation. The impacted soil will be disposed of at an approved landfill as non-hazardous waste in accordance with Rules 905 and 906. Copies of the waste manifests will be available upon request.

The Operator has added the Frenzel B15-25 flowline to its excavation list. Excavation is tentatively scheduled to commence on January 14, 2025

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation was completed at the former Frenzel B15-25 flowline and wellhead on 1/4/2024. The results of the site investigation were previously detailed in the attached of Doc. # 403794604. Groundwater was encountered and six PVC monitoring wells were installed and sampled for Table 915 constituents in groundwater.

The source will be excavated, and confirmation soil samples will be collected and analyzed for the full Table 915 suite. The proposed excavation extent is 25'x25'x3' deep. Impacted groundwater, encountered during the flowline decommissioning activities, will be monitored quarterly in accordance with the attached groundwater sampling methods and procedures plan. Soil and/or groundwater remediation plans will be updated, as needed, and submitted to ECMC in a supplemental Form 27. Monitoring wells destroyed during excavation will be reinstalled within 45 days of excavation completion.

This quarter represents the third consecutive clean quarter of groundwater sampling at the site. A no further action (NFA) designation will be requested will be requested following source removal and/or in situ remediation of impacted soil at the location, and completion of four consecutive quarters of groundwater reported at the location with concentrations of Table 915 constituents below regulatory limits. Should no additional active remediation be required a no further action (NFA) determination following laboratory confirmation.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

Yes _____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Six groundwater monitoring wells were installed to delineate the magnitude and extent of groundwater impacts (MW-1 to MW-6). The samples will be analyzed by a certified laboratory for the full suite of ECMC Table 915-1 organics and inorganics, along with PAH: acenaphthene, benz(a)anthracene, benzo(a)pyrene, dibenzo(a,h)anthracene, fluorene, pyrene, 1-methylnaphthalene, 2-methylnaphthalene. The wells will be monitored quarterly until four consecutive quarters of ECMC Table 915-1 compliant groundwater concentrations are achieved.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Supplemental Form 27

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 70000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 06/07/2022

Actual Spill or Release date, or date of discovery. 11/08/2022

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/21/2022

Proposed site investigation commencement. 07/15/2022

Proposed completion of site investigation. 12/07/2022

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/07/2022

Proposed date of completion of Remediation. 03/31/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The proposed date for completion of remediation has been updated based on the tentative excavation date of January 14, 2025

OPERATOR COMMENT

This Form 27 updates the ECMC with data collected during the Q3 2024 groundwater sampling at the location and addresses COAs from the previous forms.

403794604 COAs

- 1) A proposed background soil sample location map has been attached and a description has been included Site Investigation Report section.
- 2) Additional PAH constituents acenaphthene, benz(a)anthracene, benzo(a)pyrene, dibenzo(a,h)anthracene, fluorene, pyrene, 1-methylnaphthalene, 2-methylnaphthalene have been added to the groundwater monitoring plan, however, they were not sampled by error for the Q3 2024 sampling event.

403890238 COAs

- 1) The Operator has added the Frenzel B15-25 flowline to its excavation list. Excavation is scheduled to commence on January 14, 2025.
- 2) See the above notes about COAs on 403794604.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Chris Lattes

Title: Consultant

Submit Date: _____

Email: chrisl@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 24600

COA Type**Description**

0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403990701	MONITORING REPORT
403990702	ANALYTICAL RESULTS
403990705	MAP

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)