

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403992288

Date Received:
11/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Nash, Charlotte

(713) 589-8186

charlotte_nash@pogresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715201080

Inspection Date: 10/15/2024

FIR Submit Date: 10/16/2024

FIR Status: _____

Inspected Operator Information:

Company Name: P O & G OPERATING LLC

Company Number: 10634

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 321931

Location Name: DOLFI-615S45W Number: 35SWSW County: CHEYENNE

Qtrqtr: SWS Sec: 35 Twp: 15S Range: 45W Meridian: 6
W

Latitude: 38.698240 Longitude: -102.420850

FACILITY - API Number: 05-017- -00 Facility ID: 208572

Facility Name: DOLFI Number: 1-35

Qtrqtr: SWS Sec: 35 Twp: 15S Range: 45W Meridian: 6
W

Latitude: 38.698240 Longitude: -102.420850

CORRECTIVE ACTIONS:

1 CA# 199857

Corrective Action: Remove equipment from location to begin final reclamation process

Date: 11/15/2024

Response: CA COMPLETED

Date of Completion: 11/06/2024

Operator Comment: all equipment removed

ECMC Decision: _____

all equipment removed

--

Date: 11/13/2024 6:08:18 AM

<u>Document Number</u>	<u>Description</u>
403992288	FIR RESOLUTION SUBMITTED
403992293	field photo

Page 2 of 2