

# Inspection Photos

API: 011-06036

Operator: OXY USA INC

Inspection Date: 11/12/2024

County: BENT



## Inspection Photos



**Photo 1.** Facing west toward the location. The perennial vegetation appears to have fully reestablished.



## Inspection Photos



**Photo 2.** Facing east toward the location. The perennial vegetation appears to have fully reestablished. There is some black plastic netting that needs to be removed.



Inspection Photos



**Photo 3.** There is bunched up plastic netting that needs to be removed.



## Inspection Photos



**Photo 4.** Facing southeast toward the location. The perennial vegetation appears to have fully reestablished. There is bunched up plastic netting that needs to be removed.

