

# Inspection Photos

API: 011-06083

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 11/12/2024

County: BENT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized.



## Inspection Photos



**Photo 2.** Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized.



## Inspection Photos



**Photo 3.** Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-06083 | Date: 11/12/2024

## Inspection Photos



**Photo 4.** Facing southeast toward the wellsite and tank battery. There is a dead cow carcass laying next to the tank!



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-06083 | Date: 11/12/2024

## Inspection Photos



**Photo 5.** There was an oil leak by the outlet. There is still stained soils that need to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-06083 | Date: 11/12/2024

Inspection Photos



**Photo 6.** Facing toward the well which is temporarily abandoned. Unused equipment needs to be removed.



Inspection Photos



**Photo 7.** Facing west at the location. There are areas of the location that are bare of vegetation that need to be reseeded.

