

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 11/12/2024



Location Entrance – Photo #04834



Location – Photo #04835




## Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 11/12/2024



Location – Photo #04841



Location – Photo #04837



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 11/12/2024



Location – Photo #04839



Location – Photo #04844

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 11/12/2024



**Wildlife Entry Hazard – Photo #04842**



**Wildlife Entry Hazard – Photo #04843**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 11/12/2024



**Lack of Stabilization – Photo #04838**



**Insufficient Tracking BMPs – Photo #04845**