

# Inspection Photos

API: 099-06248

Operator: MURFIN DRILLING COMPANY

Inspection Date: 11/12/2024

County: PROWERS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the former access road.





## Inspection Photos



**Photo 2.** Facing east toward the location. The location has been leveled and debris was removed..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing northeast at the location.

