

# Inspection Photos

API: 099-06889

Operator: CHOLLA PETROLEUM INC

Inspection Date: 11/12/2024

County: PROWERS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the former access road. There are areas along the road that need to be reseeded and reclaimed.





## Inspection Photos



**Photo 2.** Facing southeast toward the location. There are tall undesirable weeds that will need to be removed and controlled.





## Inspection Photos



**Photo 3.** This abandoned pipe riser must be removed and properly abandoned.





## Inspection Photos



**Photo 4.** Facing south at the location. It appears the location was mulched and reclaimed last year however no perennial vegetation has established.





## Inspection Photos



**Photo 5.** North side of the location facing east. There is an erosion that is occurring in this area and soils are not stabilized.





## Inspection Photos



**Photo 6.** Facing northwest toward the surrounding reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources