

# Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333450

Inspection Document #: 714001449

La Plata County, CO

Township: NWNE 27 34N 9W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



Photo 1. View of well disturbance taken from the access point facing center.



API #: 067-08871, 09423



# Inspection Photos

Location Name: Francis White A2, A4

Location ID: 333450



**Photo 2.** Weedy kochia debris in the eastern portion of the pad.



Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



Photo 3. Produced water tank signs are deteriorating and no longer legible.



Inspection Photos  
Location Name: Francis White A2, A4  
Location ID: 333450



**Photo 4.** Surface owner trailers, trucks and equipment observed stored in the interim reclamation areas.