

Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325027

Inspection Document #: 714001450

La Plata County, CO

Township: SWSE 23 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Piccoli A1
Location ID: 325927



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Piccoli A1
Location ID: 325927



Photo 2. Weedy kochia debris observed on the active pad and within interim reclamation areas. Minimal desirable vegetation observed in interim reclamation areas.

Inspection Photos
Location Name: Piccoli A1
Location ID: 325927

11/5/24
340° N



Inspection Photos
Location Name: Piccoli A1
Location ID: 325927

11/5/24
357° N

