

Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 312036

Inspection Document #: 714001451

La Plata County, CO

Township: NWNW 30 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

11/5/24
325° NW



Photo 2. Surface owner equipment stored in the interim reclamation area.



Inspection Photos
Location Name: Bellino 1, 3
Location ID: 312036



Photo 3. Trash observed in the northern interim reclamation area.

Inspection Photos
Location Name: Bellino 1, 3
Location ID: 312036



Photo 4. Musk thistle observed in various patches throughout the disturbance.



Inspection Photos
Location Name: Bellino 1, 3
Location ID: 312036



Photo 5. Musk thistle observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09492, 06974

Inspection Photos
Location Name: Bellino 1, 3
Location ID: 312036

11/5/24
150° SE



Photo 6. Produced water tank signs is starting to deteriorate.

