

Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333866

Inspection Document #: 714001452

La Plata County, CO

Township: SWNE 30 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bellino 2, 4
Location ID: 333866



Photo 1. View of well disturbance taken from the access point facing center.



API #: 067-08710, 09537

Inspection Photos
Location Name: Bellino 2, 4
Location ID: 333866

11/5/24
353° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area composed of Sand Dropseed and Smooth Brome.

API #: 067-08710, 09537

Inspection Photos
Location Name: Bellino 2, 4
Location ID: 333866



Photo 3. Impacted surface material observed at both well heads.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08710, 09537

Inspection Photos
Location Name: Bellino 2, 4
Location ID: 333866



Photo 4. Musk thistle observed on the active pad and along access road.

Inspection Photos
Location Name: Bellino 2, 4
Location ID: 333866



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reference area composed predominantly of Smooth Brome and Sand Dropseed.

API #: 067-08710, 09537