

Inspection Photos

November 5th, 2024

Operator: Logos Operating - 10679

Location ID: 312051

Inspection Document #: 714001457

La Plata County, CO

Township: SESW 2 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 22A
Location ID: 312051

11/5/24
176° S



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos

Location Name: Bondad 33-9 22A

Location ID: 312051



Photo 2. View of small Musk Thistle infestation observed in the eastern and southern portions of the disturbance.

Inspection Photos
Location Name: Bondad 33-9 22A
Location ID: 312051



Photo 3. Musk Thistle observed in the western interim reclamation area.

Inspection Photos
Location Name: Bondad 33-9 22A
Location ID: 312051



Inspection Photos
Location Name: Bondad 33-9 22A
Location ID: 312051

11/5/24
286° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of large patch of Houndstongue observed in the western portion of the disturbance.

API #: 067-08138

Inspection Photos
Location Name: Bondad 33-9 22A
Location ID: 312051

11/5/24
296° NW



Photo 6. View of pasture reference area composed predominantly of Smooth Brome and Squirrel Tail.