

Inspection Photos

November 5th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325780

Inspection Document #: 714001458

La Plata County, CO

Township: SWNW 2 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barnes Leidy 1
Location ID: 325780

11/5/24
150° SE



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Barnes Leidy 1
Location ID: 325780

11/5/24
102° E



Photo 2. View of northern interim reclamation area composed of Rabbitbrush, Blue Grama, Sand Dropseed and Broom Snakeweed.

Inspection Photos
Location Name: Barnes Leidy 1
Location ID: 325780



Photo 3. View of stormwater BMP wattles in the southern portion of the disturbance that are not installed correctly and no longer functioning.

Inspection Photos
Location Name: Barnes Leidy 1
Location ID: 325780



Photo 4. Reference area composed of Juniper, Sagebrush, Broom Snakeweed and Indian Ricegrass.