

Inspection Photos

Location Name: PEPPLER-66N63W/18SESE

Location #: 305864



Photo #1

Peppler 18-44 (123-23595) Wellsite

Temporarily Abandoned | TA



Photo #2

Peppler 18-41, 18-44 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Peppler 17-32 ;

Plugged & Abandoned | PA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources