

LOCATION SUNW11, IN. 93W
OPERATOR Coors
WELL NAME Moore 1-11 MH

FIELD McHilton
COUNTY Rio Blanco
FORMATION _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____
BOP'S _____ DEPTH _____ WOC _____
CONTACT _____ CMT VOL _____ RETURNS _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: _____ PRODUCTION STRING: _____
CBL CHECKED? _____ DEPTH _____ STAGED _____
WATER DISPOSAL METHOD _____
PITS: PERMIT _____ TDS _____ SKIM TANK _____
DIMENSION: _____ SCREEN: _____ LINER: _____

LEASE SIGN: _____ TANK ID: _____ FENCED? _____
SURFACE EQUIPMENT: _____

DATE OF FINAL P&A INSPECTION 9-19-86

PLUG 1	<u>SX @</u>	SURFACE RECLAIMED?	<u>Yes</u>
PLUG 2	<u>SX @</u>	SITE CLEAN?	<u>Yes</u>
PLUG 3	<u>SX @</u>	LANDOWNER RELEASE?	_____

INSPECTOR RTB

OK



Computer - Yes