

WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

(C)  
ALREADY  
IN COMPUTER

Well Name Moore 1-11 MH API Number 05 - 103 - 07860  
Operator Coors Energy (Now Cawco) Permit # 76-0470  
Location SWNW 11-T1N-R93W County Rio Blanco  
Field McHatten (Wildcat) Inspector B. Macke

AL/PA/DA Inspection Results:

Well Status:

Pass(Y)      Fail(N)      Date 5/24/92 ND      DG      WO      PR      SI      TA     

Date of Inspection Before/During Drilling                     

Surf. Csg. Size      Setting Depth      Cmt. Vol.      WOC time       
Consistent with APD casing Program? YES      NO      Returns       
Rig      BOP'S      Stage Tool Depth      Cmt. Vol.     

Date of Inspection Before/During/After Completion                     

Prod. Csg. Set?      Completion Rig/Activity                       
Drilling Pits: Closed      Open      Wellhead Installed:      Sign: Yes      No       
Tank ID: Yes      No      N/A      Skim Tank/Pit:      Prod. Tanks: ( )      BBLs  
Equipment                      Meter Run: Yes      No       
Bradenhead Press:      Fluid: No      Yes      Type      Well Cat.     

AL/PA/DA Inspection

Date Plugged:                      Date Permit Expired:                       
Hole Plugged: Yes X No      Pits Backfilled: Yes X No       
Material Buried: Yes X No      N/A      Site Clean: Yes X No       
Bond Release OK: Yes X No      Fed      Hole Marker: Yes X No     

Found Pipe Marker

Date of Safety/Status Inspection 5/24/92

Comments: Found pipe marker w/ inscription:

"Moore 1-11 MH

SWNW Sec. 11 T1N-R93W

Rio Blanco Co, Co, Plug by Riggy Inc

Coors Energy Co.



00038532

Well restored location - vegetation well established.

Violations: Yes      No X Notice Sent: Yes      No      Date Sent: