

Inspection Photos

November 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325523

Inspection Document #: 714001477

La Plata County, CO

Township: SWSW 32 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gearhart 01-32 1
Location ID: 325523



11/12/24
287° W

Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Gearhart 01-32 1
Location ID: 325523



Photo 2. Eastern interim reclamation area composed of Western Wheatgrass, Crested Wheatgrass and Rubber Rabbitbrush.

Inspection Photos
Location Name: Gearhart 01-32 1
Location ID: 325523



Photo 3. Impacted surface material observed at well head.

Inspection Photos
Location Name: Gearhart 01-32 1
Location ID: 325523



Photo 4. Reference area composed of Smooth Brome, Pine, Antelope Bitterbrush and Gambel Oak.