

WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

(C)

Well Name Moore 5-11/MH API Number 05 - 103 - 09066
Operator Coors Energy (Now Garco) Permit # _____
Location NWNW Sect 11-T1N-R9W County Rio Blanco
Field McHatten Inspector B. Macke

AL/PA/DA Inspection Results: Well Status:
Pass(Y) X Fail(N) _____ Date 5/24/93 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes _____ No N/A X Pits Backfilled: Yes X No _____
Material Buried: Yes X No _____ N/A _____ Site Clean: Yes X No _____
Bond Release OK: Yes X No _____ Fed _____ Hole Marker: Yes _____ No N/A X

Date of Safety/Status Inspection 5/24/93

Comments: Hiked into location - Found where location had once been built years ago, but was re-contoured + well restored.



00038474

Violations: Yes _____ No X Notice Sent: Yes _____ No _____ Date Sent: _____