

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 11/14/2024



Location – Photo #04893



Location – Photo #04886

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 11/14/2024



Location – Photo #04887



Location – Photo #04890

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 11/14/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04894



Open Wellhead Cellar/No Wildlife Egress – Photo #04895