



Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#1 sign

Oct 16, 2024 1:01:04 PM  
40.35344516392797N 108.4444097802043W  
Highway 40 West  
Dinosaur  
Moffat County  
Colorado



Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#2 inside  
enclosure.



Oct 16, 2024 1:01:19 PM  
40.35351142287254N 108.44434113241732W  
Highway 40 West  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#3 pump. Note lube  
oil on pad surface.

Oct 16, 2024 1:01:23 PM  
40.3535057650879N 108.44434146769345W  
Highway 40 West  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#4 inside  
enclosure. Note: filter  
socks on ground, stored  
oily lube oil.

Oct 16, 2024 1:01:32 PM  
40.35349587444216N 108.44435705803335W  
Unnamed Road  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#4 Elk Springs #4  
wellhead

Oct 16, 2024 1:02:03 PM  
40.35346859134734N 108.44435839913785W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#6 genset adject to  
wellhead and pump  
enclosure.

Oct 16, 2024 1:02:18 PM  
40.3534386260435N 108.4442734066397W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#7 wellhead and  
tank battery for the Elk  
Springs #3.

Oct 16, 2024 1:02:38 PM  
40.35333590582013N 108.44429260119796W  
Unnamed Road  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#8 black in center  
of photo is the discharge  
point for spill 484741.

Oct 16, 2024 1:04:48 PM  
40.35282829776406N 108.4444943536073W  
Unnamed Road  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: Iles  
Location ID: 311768  
Remediation Project #: 31024  
Inspection Date: 10/16/2024

Photo#black in center of  
photo is the discharge  
point for spill 484741.

Oct 16, 2024 1:04:42 PM  
40.35282976459712N 108.4444943536073W  
Unnamed Road  
Dinosaur  
Moffat County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources