

Inspection Photos
Location Name: FRANCIS-66N64W/8NENW
Location #: 302223




Photo #1

Francis 21-8 (123-27380) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf



Photo #2

Francis 21-8 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
Site safety signage



Inspection Photos

Location Name: FRANCIS-66N64W/8NENW
Location #: 302223



Photo #3
Francis 21-8 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
Wellsite entrance




Photo #4
Francis 21-8 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
JSA: 2024-11-15



Inspection Photos

Location Name: FRANCIS-66N64W/8NENW

Location #: 302223



Photo #5

Francis 11-8, 21-8 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf

Battery sign



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources