

Inspection Photos
 Location: QB ENERGY BJU/M23A-496 Pad
 Location ID: 478266
 Date: 11/12/2024



Photo # 9018 Entrance to location



Photo # 9017 Location

Inspection Photos
Location: QB ENERGY BJU/M23A-496 Pad
Location ID: 478266
Date: 11/12/2024



Photo # 9024 Location




Photo # 9025 Location

Inspection Photos

Location: QB ENERGY BJU/M23A-496 Pad

Location ID: 478266

Date: 11/12/2024



Nov 12, 2024 at 2:55:49 PM
+39.684637,-108.140075 ±4.72m
Parachute

Photo # 9032 Location



Nov 12, 2024 at 2:59:13 PM
+39.684821,-108.140952 ±4.72m
Parachute

Photo # 9033 Location

Inspection Photos
Location: QB ENERGY BJU/M23A-496 Pad
Location ID: 478266
Date: 11/12/2024



Photo # 9034 Location



Photo # 9036 Location



Inspection Photos

Location: QB ENERGY BJU/M23A-496 Pad

Location ID: 478266

Date: 11/12/2024



Photo # 9020 Unused berm not compacted and damaged



Photo # 9022 Unused berm not compacted and damaged

Inspection Photos

Location: QB ENERGY BJU/M23A-496 Pad

Location ID: 478266

Date: 11/12/2024




Photo # 9028 Open ended piping/wildlife hazard/ available for entry by wildlife



Photo # 9041 Unused berm not compacted and damaged