


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWNE

Location ID: 335457

Date: 11/14/2024



Location – Photo #04907



Location – Photo #04911

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWNE

Location ID: 335457

Date: 11/14/2024



Location – Photo #04909



Stored Equipment – Photo #04908

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWNE

Location ID: 335457

Date: 11/14/2024



Open-Ended Line – Photo #04912



Open-Ended Line – Photo #04913

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWNE

Location ID: 335457

Date: 11/14/2024



**Wildlife Entry Hazard – Photo #04914**



**Label Does Not State Tank Capacity – Photo #04910**