

Inspection Photos
Location Name: Brophy Joe 10-14
API Number: 125-08809



1. Well sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Brophy Joe 10-14
API Number: 125-08809



3. Wet area noted around water leg of wellhead.



4. Valve on water leg that is leaking produced water.

Inspection Photos
Location Name: Brophy Joe 10-14
API Number: 125-08809



5. View of base of valve where leak is originating.



6. Well location overview.

Inspection Photos
Location Name: Brophy Joe 10-14
API Number: 125-08809



7. Well sign at remote shared gathering location.



8. Shared gathering location overview.

Inspection Photos
Location Name: Brophy Joe 10-14
API Number: 125-08809



9. Gas meter inside meter shed.



10. Damaged roof on meter shed.