

# Inspection Photos

API: 043-06230

Operator: AUSCO PETROLEUM INC

Inspection Date: 11/14/2024



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast near the abandoned well site. There were rock check dams placed below the location that will need to be removed..





## Inspection Photos



**Photo 2.** There are old degraded wattles that will need to be removed..





## Inspection Photos



**Photo 3.** Facing west at the abandoned wellsite which has been capped below grade. This area has not yet re-established perennial vegetation.





## Inspection Photos



**Photo 4.** South side of the location facing north.

